


## FFP3 Important Update for 3M 1873V+ users

We are currently experiencing temporary supply issues with the 3M 1873V+ FFP3 mask.

In the mean time when ordering the 1873+ masks you will receive a 3M 9332+ model of mask. This mask is **identical to the 1873V+** mask with the only difference being the model as noted in the 3M technical bulletin below.

There is no need for staff to face fit test to the 9332+ if they have already achieved a pass on the 1873V+, as they are compatible masks.

### 3M Technical Bulletin

A fit test outcome for this respirator model...	can help predict a fit test outcome for this respirator model(s).**	
3M™ Aura™ (3-panel flat fold)		
1873V+ (Healthcare FFP3)		9332+ (Standard FFP3) 06933+ (Standard FFP3)

#### 3M 1873V+ mask



#### 3M 9332+ mask



# Health & Safety Service

**FFP3 Important Update for 3M 1873V+ users**

---

